

GS H2 Instructions

Filling the GS H2 clearomizer is very easy and fast.

- 1- Remove the bottom by unscrewing the coil adapter.
- 2- Always check to make sure the coil is tight in the adapter before filling the body with e-liquid.
- 3- Hold the body at a slight angle and fill the body with e-liquid to about 1/8 inch from the top of the inner pipe, do not get e-liquid in the pipe.
- 4- Screw the coil adapter into the body.
- 5- Prime the new coil by taking 3-4 puffs without energizing the coil (don't push the button while taking these puffs).
- 6- The GS H2 is now ready for use.

